



FALKLAND ISLANDS GOVERNMENT

NOTICE TO MARINERS

N^o 07/2020

Stanley Harbour

FIC East Jetty

Mooring Buoy Established

The Falkland Islands Company have laid a private mooring buoy in the vicinity of the East Jetty;

Position: 51°41.515'S, 057°51.293'W

It is a yellow spherical buoy, 1200mm in diameter and made of steel.

It is currently unlit.

This mark has been laid in accordance with the Harbours and Ports Ordinance 2017, section 26 and industry best practice.

This Notice shall remain in force until further notice.

Captain C Locke,
Harbour Master,
Falkland Islands Government.

Issued on 29/06/2020